
Date	3-22-2023	Time/	2:15 PM
Inspect	tor(s) / Position:	ETCHUN	7
Site Co	onditions:		11
Sky: C	LOUDY Ground Moisture: WET	Temperatu	re: 50 °F Precipitation: Rayning
Berms	– Landfill Unit 2:		re: 50°F Precipitation: Rayning 10 Am Thunders
	ons Limiting Visibility:		
	Snow Cover		Other
X	Vegetation		None
Observ	vations:		
	Erosion / Gullies		Sudden drop in impoundment level
	Cracking / Sloughing		Actual or potential structural weakness
	Seeps / Damp Areas		Improper operation of overtopping control
	Signs of Creep		Visible release
	Failed/eroded vegetation >100sq ft.	×	No observed problems
Describ	pe findings. Identify locations on attache	d map. Attach ac	dditional pages if necessary.



Berms	s – Daliman Asn Pond		
Condit	tions Limiting Visibility:		
	Snow Cover		Other
X	Vegetation		None
Obser	vations:		
	Erosion / Gullies		Sudden drop in impoundment level
	Cracking / Sloughing		Actual or potential structural weakness
	Seeps / Damp Areas		Improper operation of overtopping control
	Signs of Creep		Visible release
	Failed/eroded vegetation >100sq ft.	×	No observed problems
Descri	be findings. Identify locations on attached	l map. Attach ad	ditional pages if necessary.
	-		



Berm	S – Lakeside Ash Pond		
Condi	tions Limiting Visibility:	į.	
	Snow Cover		Other
×	Vegetation		None
Obsei	vations:		
	Erosion / Gullies		Sudden drop in impoundment level
	Cracking / Sloughing		Actual or potential structural weakness
	Seeps / Damp Areas		Improper operation of overtopping control
	Signs of Creep		Visible release
	Failed/eroded vegetation >100sq ft.	×	No observed problems
Descr	ibe findings. Identify locations on attached	l map. Attach ad	ditional pages if necessary.
	THE STATE OF THE S		



35 IAC 845 Weekly Inspection Form

Berms – Lime Softening Ponds Conditions Limiting Visibility: □ Snow Cover □ Other _____ ✗ Vegetation □ None Observations: ☐ Erosion / Gullies ☐ Sudden drop in impoundment level □ Cracking / Sloughing ☐ Actual or potential structural weakness □ Seeps / Damp Areas ☐ Improper operation of overtopping control □ Signs of Creep □ Visible release ☐ Failed/eroded vegetation >100sq ft. No observed problems Describe findings. Identify locations on attached map. Attach additional pages if necessary.



Location:			
Location: Description of Repair:			
DC301	iplion of repair.		
Effect	iveness of Repair:		
	Problem completely remedied		
	Problem partially remedied (explain below):		
	Problem not remedied (explain below):		
	Progression of trouble into new area (explain):		
	s of Previous Repair(s):		
	ion:		
Descr	ription of Repair:		
Effect	iveness of Repair:		
П			
	Problem not remedied (explain below):		
	Progression of trouble into new area (explain):		
	Trogression of trouble into new area (explain).		

Additional Notes:	

	············
	<u></u>