
Date	7-26-2023	Time	9:00 AM				
Inspector(s) / Position: TIM KETCHUM							
Site Conditions: LIGHT Sky: <u>CLOUDS</u> Ground Moisture: DRY Temperature: 83°F Precipitation: NONE							
Berms – Landfill Unit 2:							
Conditions Limiting Visibility:							
	Snow Cover		Other				
×	Vegetation		None				
Observations:							
	Erosion / Gullies		Sudden drop in impoundment level				
	Cracking / Sloughing		Actual or potential structural weakness				
	Seeps / Damp Areas		Improper operation of overtopping control				
	Signs of Creep		Visible release				
	Failed/eroded vegetation >100sq ft.	×	No observed problems				
Describe findings. Identify locations on attached map. Attach additional pages if necessary.							



Berms	s – Dallman Ash Pond					
Condit	ions Limiting Visibility:					
	Snow Cover		Other			
×	Vegetation		None			
Observ	vations:					
	Erosion / Gullies		Sudden drop in impoundment level			
	Cracking / Sloughing		Actual or potential structural weakness			
	Seeps / Damp Areas		Improper operation of overtopping control			
	Signs of Creep		Visible release			
	Failed/eroded vegetation >100sq ft.	X	No observed problems			
Describe findings. Identify locations on attached map. Attach additional pages if necessary.						



35 IAC 845 Weekly Inspection Form

Berms - Lakeside Ash Pond

Conditions Limiting Visibility:						
□ Snow Cover		Other				
★ Vegetation		None				
Observations:						
□ Erosion / Gullies		Sudden drop in impoundment level				
□ Cracking / Sloughing		Actual or potential structural weakness				
✓ Seeps / Damp Areas		Improper operation of overtopping contro				
□ Signs of Creep		Visible release				
□ Failed/eroded vegetation >100sq ft.		No observed problems				
Describe findings. Identify locations on attached map. Attach additional pages if necessary.						
V = SEEP I OCATIONI						



35 IAC 845 Weekly Inspection Form

Berms - Lime Softening Ponds

□ Signs of Creep

Conditions Limiting Visibility:

□ Snow Cover □ Other □

Vegetation □ None

Observations:
□ Erosion / Gullies □ Sudden drop in impoundment level
□ Cracking / Sloughing □ Actual or potential structural weakness
□ Seeps / Damp Areas □ Improper operation of overtopping control

□ Visible release

☐ Failed/eroded vegetation >100sq ft. ☐ No observed problems

Describe findings. Identify locations on attached map. Attach additional pages if necessary.

X = SEEP LOCATION

(SMAIL PUDDLE WITH NO FLOW



Areas of Previous Repair(s):			
Location:			
Descr	iption of Repair:		
Effecti	iveness of Repair:		
	Problem completely remedied		
	Problem partially remedied (explain below):		
	Problem not remedied (explain below):		
	Progression of trouble into new area (explain):		
لسا			
Areas	of Previous Repair(s):		
Locati			
	iption of Repair:		

Effect	iveness of Repair:		
	Problem completely remedied		
	Problem partially remedied (explain below):		
	Problem not remedied (explain below):		
	Progression of trouble into new area (explain):		

Additional Notes:					
					
	· · · · · · · · · · · · · · · · · · ·				
		William I			

	· · · · · · · · · · · · · · · · · · ·				
		······································			
		<u> </u>			