
Date 10/20/21	Time			
Inspector(s) / Position: Schy Wil	<i>lmore</i>			
Site Conditions:				
Sky: Partly Clouds round Moisture: Vamp	Temperature: <u>65</u> Precipitation: <u>None</u>			
Berms – Landfill Unit 2:				
Conditions Limiting Visibility:				
□ Snow Cover	□ Other			
X Vegetation	□ None			
Observations:				
☐ Erosion / Gullies	□ Sudden drop in impoundment level			
☐ Cracking / Sloughing	□ Actual or potential structural weakness			
☐ Seeps / Damp Areas	☐ Improper operation of overtopping control			
☐ Signs of Creep	☐ Visible release			
☐ Failed/eroded vegetation >100sq ft.	No observed problems			
Describe findings. Identify locations on attached map. Attach additional pages if necessary.				



Berms	s – Dallman Ash Pond				
Condit	ions Limiting Visibility:				
	Snow Cover		Other		
×	Vegetation		None		
Obser	vations:				
	Erosion / Gullies		Sudden drop in impoundment level		
	Cracking / Sloughing		Actual or potential structural weakness		
	Seeps / Damp Areas		Improper operation of overtopping control		
	Signs of Creep		Visible release		
	Failed/eroded vegetation >100sq ft.	×	No observed problems		
Describe findings. Identify locations on attached map. Attach additional pages if necessary.					



35 IAC 845 Weekly Inspection Form

Conditions Limiting Visibility: □ Snow Cover □ Other □ Vegetation □ None Observations: □ Erosion / Gullies □ Sudden drop in impoundment level □ Cracking / Sloughing □ Actual or potential structural weakness □ Seeps / Damp Areas □ Improper operation of overtopping control

□ Visible release


No observed problems

Describe findings. Identify locations on attached map. Attach additional pages if necessary.

Berms - Lakeside Ash Pond

□ Signs of Creep

☐ Failed/eroded vegetation >100sq ft.



35 IAC 845 Weekly Inspection Form

Berms – Lime Softening Ponds

Condit	ions Limiting Visibility:			
	Snow Cover		Other	
X	Vegetation		None	
Obser	vations:			
	Erosion / Gullies		Sudden drop in impoundment level	
	Cracking / Sloughing		Actual or potential structural weakness	
	Seeps / Damp Areas		Improper operation of overtopping control	
	Signs of Creep		Visible release	
	Failed/eroded vegetation >100sq ft.	X	No observed problems	
Describe findings. Identify locations on attached map. Attach additional pages if necessary.				



Areas of Previous Repair(s):					
Location:					
	ption of Repair:				

Effecti	veness of Repair:				
	Problem completely remedied				
	Problem partially remedied (explain below):				
	Problem not remedied (explain below):				
	Progression of trouble into new area (explain):				
Areas	of Previous Repair(s):				
Locati	on:				
Descri	iption of Repair:				

Effecti	veness of Repair:				
	Problem completely remedied				
	Problem partially remedied (explain below):				
	Problem not remedied (explain below):				
	Progression of trouble into new area (explain):				

Additional Notes:	
	//
	Military and the second