


Date Inspec	3-23-2022 tor(s) / Position:	Time SETCHUM	1:00 PM		
Site C	onditions:	_	RAW AllMORI		
Sky:	Ground Moisture:	Temperatur	e: 52°F Precipitation: 6:30 - Noon		
	– Landfill Unit 2:				
Condit	ions Limiting Visibility:				
	Snow Cover		Other		
×	Vegetation		None		
Observ	vations:				
	□ Erosion / Gullies		Sudden drop in impoundment level		
	Cracking / Sloughing		Actual or potential structural weakness		
	Seeps / Damp Areas		Improper operation of overtopping control		
	Signs of Creep		Visible release		
	Failed/eroded vegetation >100sq ft.	X	No observed problems		
Descri	be findings. Identify locations on attacl	ned map. Attach ad	ditional pages if necessary.		



Berms	s – Dallman Ash Pond					
Condit	ions Limiting Visibility:					
	Snow Cover		Other			
X	Vegetation		None			
Obser	vations:					
	Erosion / Gullies		Sudden drop in impoundment level			
	Cracking / Sloughing		Actual or potential structural weakness			
	Seeps / Damp Areas		Improper operation of overtopping control			
	Signs of Creep		Visible release			
	Failed/eroded vegetation >100sq ft.	X	No observed problems			
Describe findings. Identify locations on attached map. Attach additional pages if necessary.						
***************************************						



Berms	s – Lakeside Ash Pond		
Condit	tions Limiting Visibility:		
	Snow Cover		Other
×	Vegetation		None
Obser	vations:		
	Erosion / Gullies		Sudden drop in impoundment level
	Cracking / Sloughing		Actual or potential structural weakness
	Seeps / Damp Areas		Improper operation of overtopping control
	Signs of Creep		Visible release
	Failed/eroded vegetation >100sq ft.	X	No observed problems
Descri	be findings. Identify locations on attached map. Atta	ach ad	ditional pages if necessary.
<del>*************************************</del>		······································	
			***************************************
***************************************			



#### 35 IAC 845 Weekly Inspection Form

#### **Berms – Lime Softening Ponds** Conditions Limiting Visibility: □ Snow Cover □ Other \_\_\_ ▼ Vegetation □ None Observations: □ Erosion / Gullies □ Sudden drop in impoundment level ☐ Cracking / Sloughing □ Actual or potential structural weakness □ Seeps / Damp Areas ☐ Improper operation of overtopping control □ Signs of Creep □ Visible release ☐ Failed/eroded vegetation >100sq ft. No observed problems Describe findings. Identify locations on attached map. Attach additional pages if necessary.



Areas of Previous Repair(s):					
Location:					
Descr	Description of Repair:				
	iveness of Densir:				
	iveness of Repair:				
	Problem completely remedied				
	Problem partially remedied (explain below):				
	Problem not remedied (explain below):				
	Progression of trouble into new area (explain):				
Areas	of Previous Repair(s):				
Locati					
	iption of Repair:				
D000i	puori oi repuir.				
Effect	iveness of Repair:				
	Problem completely remedied				
	Problem partially remedied (explain below):				
	Problem not remedied (explain below):				
	Drawragion of trauble into new erea (combin)				
	Progression of trouble into new area (explain):				

Additional Notes:	